


the



SERVICEMAN



VOLUME XXXI JANUARY THROUGH DECEMBER, 1957

© 1958 GENERAL
MOTORS CORP.

1957 — INDEX — 1957

A	Page
AFA's:	
A/C Compressor, Need Full Information	28
Insert Correct Radio Serial Number	26
Warranty Parts Return List Issued	49
Air Bellows, Proper Positioning in Air Dome	83
Air Cleaner and Resistor Contact, Avoid	71
Air Conditioner:	
Adding Oil to Series 75 Compressors	59
Air Flow Corrections	Supp. 5
Changes in 1957 Series 75 Cars	40
Check Outside Air Valve Control Escutcheon	36
Check Three Possible Hose Interference Conditions	63
Check Tightness of Harmonic Balancer Bolt	Supp. 5
Complete Clutch Plate Assembly Now Available	62
Correct Usage of Springs and Shims in Kits	59
Diagnosis	Supp. 3
Diagnosis Chart Correction	50
Eliminate Air Noise on 75 Series Cars	22
Evaporator Assembly Removal and Installation, 1957	54
Freon Compressor Clutch Cover	29
Full Information Needed on Compressor AFA's	28
Installation Kit Instructions Revised	44
Instrument Panel Upper Section—Removal	14
Location of Low Pressure Hoses on 75 Series Cars	63
Idle Speed Control Adjustment	78
List Correct Number on Compressor AFA's	71
One Seal Fits All 1955 A/C Compressors	16
Pre-Season Check-Up of System Now Due	39
Procedure For Adding Oil to Compressors	47
Service Parts Available For Freon Compressor	19
Test By-Pass Valves Prior to Replacement	37
Air Flow, Corrections, Air Conditioner	Supp. 5
Air Seal, Power Brake, Reversed	29
Air Suspension:	
Cars in Dealer Showrooms	82
Compressor Slings Oil	Supp. 6
Ride Not Related to Line Pressure	79
Tubing Nuts, Tighten Carefully	49

A (Cont'd)	Page
Antenna:	
Drain Holes	Supp. 3
Electric, 1957 Assembly Conditions	62
Motor Feed Wire Clip Now Located Higher	19
Repair Kit Available For Service	39
Anti-Freeze Offered by Factory in Three Options	22
Anti-Freeze, Permanent, Available Year-Round	45
Appointments:	
Adams, D. G.	67
Beaubien, P. D.	40
Borgsdorf, D. C.	67
Burkholder, J. E.	66
Campbell, F. J.	24
Conway, W. E.	24
Dickinson, J. T.	48
Dittmer, M. W.	56
Dunn, J. A.	49
Foulke, R. L.	68
Furnival, C. R.	67
Goldnetz, J. K.	56
Heick, W. F.	56
Jackman, R. A.	66
McNulty, F. J.	66
Morgan, B. L.	56
Murray, F. H.	17
Nekervis, J. T.	40
North, W. G.	66
Parsell, R. W.	67
Pierce, G. R.	66
Rea, R. S.	67
Roche, J. M.	17
Sandstrom, J. R.	67
Saxe, F. L.	48
Soukup, T. G.	66
Wagner, C. C.	67
Arm Mounting Bolt, New Lower Suspension, Being Used	38
Arm, Rocker, New Higher Torque Required	13
Arm Rest Material, Replacement of Formed Plastic	29
Aromatic Fuel Can Spell Trouble For Car Finishes	59
Ashtray and Door Assemblies, Front, Repair of	19
Automotive Service Work, Opportunity Unlimited	70
Autronic Eye Wire, Relocate to Prevent Short	27
Axle Ratio, Rear, Identification Number	14
Base Clamp, Front Cigar Lighter, Longer	57
Battery Cable Retainer Clip, Position Correctly	44
Bearing, Rear Main, Seal	58
Bearing, Rear Wheel, "O" Ring Seal Improved	65

B	Page
Bellows, Proper Position in Air Dome	83
Belt Tensioner Gage Released for Field Use	46
Blades, Check Wiper Arm When Wind Affects Movement	50
Body Bolt Installation	Supp. 1
Body Styles, 1958	78
Bolt:	
Harmonic Balancer	29
Harmonic Balancer, New Design	37
Lower Control Arm Mounting, Check Torque	23
New Lower Suspension Arm Mounting, Now Being Used	38
Box, Instrument Panel Compartment	29
Brace Corrects Vibration at Power Steering Pump	83
Brakes:	
Adjustment Affects Pedal Return Travel	81
Attention to Detail Assists in Correcting Brake Pull	57
Bleeding of Power Unit Eliminates Brake Noise	18
Breaking-In of New and Replacement Brake Linings	Supp. 5
Check Brake Pedal Travel From Correct Location	46
Drum, Machining Correction	12
Drum Silencer Springs	18
Fluid Seepage	Supp. 6
Hydrovac Poppet Valves Replaceable in Field	30
Pinched Hose Reduces Power Brake Assist	24
Power Brake Hydraulic Cylinder, Seal Added	41
Reversed Air Seal Acts as Second Hydraulic Seal	29
Route Hydraulic Brake Lines to Avoid Chafing	55
Squeak May be Caused by Spring Washer	51
Variation of Parts Used on Some Broughams	72
Brougham:	
Adjust Headlamp Aiming	80
Air Conditioner Diagnosis Chart Correction	50
Compressor Oil Inlet Fittings Modified	71
Introduction of	31 through 36
Longer Wiper Blades Used	66
New Leveling Valve Link Nuts Used	66
Normal Standing Height Can Be Varied	67
Radio Foot Control Switch	58
Tighten Air Suspension Tubing Nuts Carefully	49
Undercoating Not Recommended	70
Upper Control Yoke	50
Windshield Installation Procedure	61

B (Cont'd)

	Page
Bumpers Relieve Deck Lid Contact at Upper Corners	40

C

Cadillac National Field Service Organization	8
Cadillac Training Center Instructors	10
Cadillac "Serviceman" Completes Its 30th Year	4
Cadillac Shop Manual Supplement, 1958, To Be Ready This Month	72
Camber Adjustments	46
Carburetor:	
Carter, Now Available For Replacement	29
Fast Idle Changes In Rochester	65
Flooding	Supp. 3
Idle Speed Control Adjustment, Air Conditioner	78
Latest 1957 Rochester Improvements	28
Reset Choke Thermostat For Winter Rochester Carburetor Conditions, 1957	Supp. 4
Rochester Changes, 1957	Supp. 1
Rochester, 1957, Float Drop Adjustment Revised	15
Service Information Book, Carter AFB Carburetor	64
Carpet Cleaning, Recommended Procedure	49
Carter AFB Carburetor Service Information Book	64
Carter Carburetor Now Available For Replacement	29
Caster, Camber and Toe-In Adjustments	46
Chart Correction, Air Conditioner Diagnosis	50
Check Links, Glove Box, May Become Disengaged	13
Choke Thermostat, Carburetor, Reset For Winter	80
Cigar Lighter, Front Base Clamp is Longer	57
Cigar Lighters, Rework, To Prevent Blown Fuse	23
Clamps, Tie Rod, Rotate to Prevent Interference	18
Classes, Training Center, Well Attended In 1957	79
Clevises, Hold Down, Rapid Return Requested	23
Clips Help Position Fog and Parking Lamp Wires	13
Clip To Secure Six-Way Seat Wire Connector, Use	21
Clocks, 1957, Interchangeability	58
Clocks, Inoperative	29
Club Meetings and Award Presentations:	
Albany, New York	15
Albuquerque, New Mexico	48
Alhambra, California	80
Birmingham, Alabama	15-41
Buffalo, New York	84
Burbank, California	39
Canton, Ohio	56-60
Chicago, Illinois	72-84
Columbia, South Carolina	56-64
Columbus, Ohio	60
Dallas, Texas	47-48
Denver, Colorado	72
East Aurora, New York	80
Hinsdale, Illinois	56
Houston, Texas	24-84
Indianapolis, Indiana	60
Jacksonville, Florida	56
Kalamazoo, Michigan	60
Kansas City, Missouri	24
Los Angeles, California	48-60
Nashville, Tennessee	48
Milwaukee, Wisconsin	60-84
Minneapolis, Minnesota	64
Mobile, Alabama	68

C (Cont'd)

	Page
Oklahoma City, Oklahoma	80
Panama City, Florida	58
Philadelphia, Pennsylvania	48-60-68
Phoenix, Arizona	84
Providence, Rhode Island	72
San Francisco, California	48
Sioux City, Iowa	48-80
Springfield, Massachusetts	56-64
St. Louis, Missouri	64
Waterloo, Iowa	30
Clubs, Service Manager, Enjoying Great Success	72
Clutch Cover, Freon Compressor	29
Clutch Plate, Complete Assembly Now Available	62
Coil Spring, Rear, Part Number, 6239D	84
Compressor:	
AFA's, List Correct Number	71
A/C, Procedure For Adding Oil	47
Air, Slings Oil	Supp. 6
Brougham Air, Oil Inlet Fittings Modified	71
Convertible Coupes, Drain Hoses Eliminated	46
Convertible Rear Window Zipper Damaged	29
Convertible Tops, Frequent Cleaning Best	12
Convertible Top Wicking, New Kit Provides Fixes	63
Cooling System Inhibitor, Be Careful When Using	71
Cooling System Torque Specification Change	12
Cowl Fresh Air Vent Grilles	50
Coupling Valve Body	40
Craftsman's League, Join Before the Deadline	22
Craftsman's League Examination:	
Name Code Number Added	41
Qualifying Grade Lowered	58
Question Trips Many Servicemen	53

D

DC-4X Silicone, Apply to Rubber Weatherstrips	13
Dealer Showroom Display of Air Suspension Cars	82
Deck Lid:	
Contact at Upper Corners Eased By Bumpers	40
Holes, Seal to Stop Trunk Water Leaks	16
Opening Can Be Prevented by Lock Pin Pressure	30
Power Closing Units	Supp. 6
Diagnosis of Minor Radio Troubles	52
Dipstick, Transmission Fluid	12
Directional Signal Circuit Uses Heavier Fuses	26
Door Assemblies and Front Ash Tray, Front, Repair of	19
Door, Front and Rear 75 Window Frames, Loose	38
Door, Inner Panel, Water Deflector, Seal Properly	70
Door, Inner Panel, Waterproof Paper Drag Link Height, Specifications Changed, 1957	24
Drain Holes, Antenna	Supp. 3
Drain Hose, Eliminated on Convertible Coupes	46
Drum, Brake, Machining Corrected	12
Drum, Brake, Silencer Springs	18
"Dusty Rose" Metallic Paint Formula Changed	28

E

Eldorado Brougham, Introduction	31-36
Eldorado Front Fender Ornaments, Sealing	Supp. 5
Electric Antenna Assembly Conditions, 1957	62

E (Cont'd)

	Page
Electric Clocks, 1957, Interchangeability	58
Electrical Specifications, Shop Manual, Revisions	36
End Play, Rear Unit	50
Engine, Cold, Caution Stressed When Warming Up	29
Evaporator Assembly Removal and Installation, 1957	54
Examinations, Craftsman's League:	
Name Code Number Line Added	41
Qualifying Grade Lowered	58
Question Trips Many Servicemen	53

F

Factory Parts Warehouse Keeps Pace With Market	4
Staff Members	6
Factory Service Department Staff Members	5
Fall Conditioning Program	69
Field Representatives, Parts Warehouse	6
Flat Rate Schedule, 1958 Edition, Released	78
Fluid Change, Hydra-Matic, Recommended Frequently	40
Fluid Change May Prevent 2-3 Shift Noise	70
Foreign Country Octane Requirements	14
Fog and Parking Lamp, Condensation Corrected	23
Fog and Parking Lamp Wires, Clips Help Position	13
Frame Contact Hoist, Position Pads Correctly When Lifting 1957 Cars	16
Frame Contact Hoist, Use on 1958 Cars	Supp. 6
Front Seat Chuck Eliminated by Tensioner Spring	15-25
Front Seat, Manual, Unlocking, Caused by Excessive Tension	37
Front Suspension Friction	Supp. 6
Front Suspension Upper Arm Mounting Bolts	51
Fuel, Aromatic, Can Spell Trouble For Car Finishes	59
Fuse, Heavier, Now Used in Two 1957 Circuits	26

G

Gage, Belt Tensioner, Released For Field Use	46
Gap, Correction of, At Rear Quarter Gas Pedal, Applications of Silicone Ease Sticking	40
Gear Shift and Turn Signal Knobs, Replacement	40
General Service Managers	7
Glass, Window, Rear Door, Removal Procedure	30
Glove Box:	
Check Links May Become Disengaged	13
Light Switch	29
Grilles, Cowl Fresh Air Vent	50

H

Harmonic Balancer:	
Bolt, Check Tightness	Supp. 5
Bolt, New Design, Recommended	37
Bolt, Retorquing Recommended	29
Headlamp Aiming, Adjust on Eldorado Brougham	80
Heat Control Valve, Watch For "B" Type	61
Heater, Blower Motor Resistor, Eldorado, Relocated	27
Heater, Four Adjustments Increase Efficiency	25
Hold Down Clevises, Rapid Return Requested	23

H (Cont'd)

	Page
Hoist, Frame Contact, On 1958 Cars	Supp. 6
Hood Lock and Latch Engagement	37
Hoods, 1957, Exercise Care When Closing	62
Hose:	
A/C, Three Possible Interference Conditions	63
Drain, Eliminated in Convertible Coupes	46
Low Pressure, Location of, on 75 A/C Cars	63
Pinched, Reduces Power Brake Assist	24
Hydra-Matic:	
Early Fluid Change May Prevent 2-3 Shift Noise	70
Latest 1957 Revisions	66
New Double Orifice Oil Supply Incorporated in 1958 Transmission	Supp. 6
New Procedure Simplifies 1957 Removal	16
New SpiraloX Snap Rings on 1958 Transmission	83
Noises Corrected By Simple Fixes	18
Rear Unit End Play	50
Recommend Frequent Fluid Change	40
Spacer Plate, New, Use Limited	70
Spacer Shim Positions Front Seal	13
Transmission Fluid Dipstick	12
Use Correct Oil Cooler on All Series Cars	61
Hydraulic Valve Lifter and Push Rod	Supp. 2
Hydraulic Valve Lifters Have Optional Design	24

I

Inhibitor, Cooling System, Be Careful When Using	71
Instructions, A/C Installation Kit, Revised	44
Instructors, Training Center	10
Instrument Panel:	
Compartment Box	29
Cover, Retained By Hidden Screws	28
Upper Section Removal—A/C Cars	14
Introducing the 1958 Cadillac	73
Introducing the Eldorado Brougham	31-36

K

Kit, Antenna Repair, Available For Service	39
Kit Provides Fixes For Convertible Wicking	63
Knob, A/C Outside Air Valve Control Escutcheon, Check	36

L

Latch and Hood Lock Engagement	37
League, Craftsman's, Join Before Deadline	22
Leaks, Trunk Water	84
Leather Cleaning Agents, Use Care When Choosing	59
Leather Trim, Replacement, Under Warranty	14
Letters From "Serviceman" Readers	11
Leveling Valve Link Nuts, New, Used on Brougham	66
Lifters, Valve, New Type For Past Model Engines	84
Light Switch, Glove Box	29
Lighters, Cigar, Rework to Prevent Blown Fuse	23
Line Pressure Not Related to Air Suspension Ride	79
Lines, Hydraulic Brake, Route to Avoid Chafing	55
Linings, Brake, Breaking-in of New and Replacement	Supp. 5

L (Cont'd)

	Page
Lock Pin Pressure Can Prevent Deck Lid Opening	30
Lower Control Arm Mounting Bolt Torque, Check	23
Lubrication, Windshield Wiper Cam	40

M

Manual Seat Unlocking, Caused by Excess Tension	37
Manual, Shop, Past Model	84
Manual, Shop, Supplement 1958 Ready This Month	72
Mats, Rubber, 1957 Front Contour	29
Micro-Switch, Trunk Lock, Now Replaceable in Field	45
Most Important Single Step to Owner Satisfaction	51
Motor Feed Wire Clip, Antenna, Now Located Higher	19
Mounting Bolts, Upper Arm, Front Suspension	51

N

National Safety Check Campaign	43
Noises:	
Brake Squeak May Be Caused by Spring Washer	51
Clinking Noise Traced to Oil Filter Line	12
Early Fluid Change Prevents 3-2 Shift Noise	70
Eliminate Air Noises on 75 Series A/C Cars	22
New Cure For Whistling at Shift Points	27
Power Unit Bleeding Eliminates Brake Noise	18
Rear Spring	Supp. 2
Tensioner Spring Stops Front Seat Chuck	15
Transmission Noises Corrected By Simple Fixes	18
Nut, Pitman Arm Shaft Retaining, Recheck Torque	45

O

Obituary, J. L. Wilson	56
Octane Requirement For Traveling Owners	14
Oil Cooler, Use Correct One on All Series Cars	61
Oil Filter Line, Clicking Noise	12
Oil Leaks at Rear Wheel Bearings	62
Oil, Procedure When Adding to Series 75 A/C Compressor	59
Ornaments, Seal Front Fender Attaching Screw on Eldorado	Supp. 5
Owner Satisfaction, the Most Important Single Step	51

P

Pads, Position Correctly When Lifting 1957 Cars on Frame Contact Hoist	16
Paint Formula, "Dusty Rose" Metallic, Changed	28
Paper, Waterproof	29
Parking Brake Adjustment Affects Pedal Return Travel	81
Parking and Fog Lamp Condensation Corrected	23
Parking and Fog Lamp Wires, Clips Help Position	13
Parts Managers With 30-Year Awards	11
Parts Available For Freon Compressor	19
Parts Warranty Return List, Issued	49
Parts Warranty Shipments Received	72
Parts Warehouse, Factory:	
Field Representatives	6

P (Cont'd)

	Page
Keeps Pace With Market	4
Staff Members	6
Pedal, Brake, Check Travel From Correct Location	46
Pipe Filler, Seal, Guards Pipe From Dirt Accumulation	27
PIR Reports, Properly Filled-In	78
PIR's, Report 1957 Product Problem Promptly	12
Pistons, Two Types, Used in 1957 Production	65
Pitman Arm Shaft Retaining Nut, Recheck Torque	45
Propeller Shaft Assemblies, Complete, Available	47
Pump Brace, Power Steering, Corrects Vibration	83
Pump Cover Torque, Power Steering	Supp. 6
Pumps, Steering, Some 1958 Used in Late 1957 Cars	79
Push Rod and Hydraulic Valve Lifter	Supp. 2

Q

Quarter, Rear, Water Leaks	Supp. 5
Question, Craftsman Examination, Trips Many Servicemen	53
Qualifying Grade Lowered, Craftsman's League	58

R

Radiator Air Deflector to Front Bumper Seal	67
Radio:	
Brougham, Foot Control Switch	58
Diagnosis and Service Information, 1957	52
Diagnosis and Service Procedure Addition	58
Insert Correct Serial Number on AFA's	26
Rear Speaker, Vibration	65
Troubles, Diagnosis Chart	52
Resistor and Air Cleaner Contact, Avoid	71
Resistor, Eldorado Heater Blower Motor, Relocated	27
Retainer Clip, Battery Cable, Position Correctly	44
Retirements:	
Bickel, E. J.	30
Olds, Roy	37
Rice, J. W.	68
Riding Complaints, Front Suspension Friction	Supp. 6
Roche, J. M., Now Cadillac General Manager	17
Rochester Carburetor:	
1957 Changes	Supp. 1
1957 Conditions	Supp. 4
Fast Idle Changes	65
Float Drop Adjustment Revised, 1957	15
Latest 1957 Improvements	28
Rocker Arm Cover, New, Requires Higher Torque	13
Rocker Arm Cover Tightening Procedure	41
Round Table:	
Charts:	
Against The Flood	54
Around The Horn	68
Clean-Up Squad, The	41
Fair and Cooler	48
Ride To Remember, A	13
Service in Shorts	30
Shifting into 1957	24
Films:	
Cadillac, The 1958	80
Deadline	84
Last Laugh	48
Lure, The	72

R (Cont'd)

	Page
More Likeable Guy, A	68
Mr. Quilby's Terrible Crime	13
Nose For News, A	41
Solid Lead Balloon, The	24
Vanishing Point	30
Rubber Mats, Front, Contour	29

S

Safety Check Campaign	43
"Safety Service", Mail Piece Sent To Owners	59
Sales and Service, Cadillac, Under New Leadership	17
Schedule, Flat Rate, 1958 Edition Released	78
Screws, Hidden, Retain Instrument Panel Cover	28
Seal, Fits All 1955 A/C Compressors . .	16
Seal, Radiator Air Deflector to Front Bumper	67
Seal, Rear Main Bearing	58
Seal, Rear Wheel Bearing "O" Ring, Improved	65
Seal Added to Power Brake Hydraulic Cylinder	41
Seal Door Inner Panel Water Deflector Properly	70
Seal Guards Filler Pipe From Dirt Accumulation	27
Seat Adjusters, Six-Way, Utilize Plastic Slide	83
Seat, Six-Way Power, Wire Relocations	44
Seat, Six-Way, Use Clip to Secure Wire Connector	21
Seats, Six-Way, Become Inoperative Due to Detached Solenoid	23
Service Department Factory Staff Members	5
Service Information and Radio Information, 1957	52
Service Manager Clubs Enjoying Great Success	72
Service Managers, General	7
Service Managers Presentation of Diplomas and Pins:	
Baker, K. H.	60
Beaver, W. E.	64
Bruederle, R.	60
Dansek, E. J.	64
Davis, J. G.	64
Davis, O.	64
Harling, J.	30
Harrison, C. B.	64
Holm, F. E.	64
Johnson, C. D.	56
Judson, W. C.	68
McCormick, T. A.	56
Pontius, R. R.	60
Porterfield, K. S.	60
Risberg, C.	59
Small, T. R.	68
Service Managers, Wholesale	7
Service Managers With 30 Year Awards	11
Service Organization, Field	8
Service Procedure and Radio Diagnosis Addition	58
"Serviceman," Cadillac, Completes Its 30th Year	4
"Serviceman" Corrections:	
Autronic Eye Wire Clearance Notch Correct Float Toe Adjustment	45
Radio Diagnosis and Service Procedure Additions	58
Use of New Hydra-Matic Spacer Plate Limited	70
"Serviceman" Readers, Letters From Shaft, Propeller, Torque Tightness . .	18
Shim, Spacer, Positions Hydra-Matic Front Seal	13
Shop Manual Corrections and Additions:	
Brake Drum, Machining Correction .	12

S (Cont'd)

	Page
Check Brake Pedal Travel From Correct Location	46
Change Cooling System Torque Specifications	12
Cooler Spark Plugs May Be Used in 1957 Cars	22
1957 Drag Link Height Specifications Changed	24
Four Adjustments Increase Heater Efficiency	25
Instrument Panel Upper Section Removal—A/C Cars	14
Propeller Shaft Torque Tightness . .	18
Rear Axle Ratio Identification Numbers, 1957	14
Electrical Specifications Revised . .	36
Valve Spring Specifications, 1957 . .	18
Shop Manual, 1958, To Be Ready This Month	72
Shop Manuals, Past Model	84
Silicone, Applications, Ease Sticking Gas Pedal	40
Silicone, DC-4X, Apply to Rubber Weatherstrips	13
Speaker, Rear, Radio Vibration Correction	65
Six-Way Seat Adjusters Utilize Plastic Slide	83
Snap Rings, New Spiralox on 1958 Transmissions	83
Solenoid, Seat Spinning Nut, Detached Solvent, Washer, Protects Glass Jar From Breaking	79
Spark Plugs, Cooler, May Be Used in 1957 Cars	22
Spiralox Snap Rings Used On 1958 Transmission	83
Spring:	
6239D, Rear Coil, Part Number . .	84
Rear Liners, Replacement Procedure	38
Rear, Noise	Supp. 2
Tensioner, Install to Stop Front Seat Chuck	15
Valve, 1957 Specifications	18
Washer May Cause Brake Squeak . .	51
Spring Conditioning	42
Springs and Shims in A/C Kits, Correct Usage	59
Stabilizer Bar, May Rub Front Tires on 1957 Cars	36
Steering Pump Cover Torque	Supp. 6
Steering Pumps, Some 1958 Used in Late 1957 Cars	79
Stoplight Malfunctions Cured by Minor Adjustments	15
Strip, Stainless Steel	29
Styles, Body, 1958	78
Sun Glare, Windshield, Can Be Reduced	62
Supplement, 1958 Shop Manual, To Be Ready This Month	72
Switch, Foot Control, Brougham Radio	58
Switches, Power Window, Correction of Sticking	55

T

Tensioner Spring Eliminates Front Seat Chuck	55
Thirty-Year Awards	11
Tie Rod Clamps, Rotate to prevent Interference	18
Tire Pressure, New Car	12
Tires, Front, May Rub Stabilizer Bar Toe-In Adjustments	36
Toe-In Revision, 1958	79
Tools, Special, Belt Tensioner Gage .	46
Top Gap, Folding, Correction at Rear Quarter	58
Tops, Convertible, Frequent Cleaning Best	12
Training Center Classes Well Attended in 1957	79

T (Cont'd)

	Page
Trim, Leather, Replacement Under Warranty	14
Trunk Lock Micro Switch Now Replaceable in Field	45
Trunk Water Leaks	16-84
Tubing Nuts, Air Suspension, Tighten Carefully	49
Turn Signal and Gear Shift Knobs, Replacement	40
TV Setting, 1958	Supp. 6

U

Undercoating, Not Recommended on Eldorado Brougham	70
--	----

V

Valve Design, Hydraulic, Optional . .	24
Valve, Heat Control, Watch for "B" Type	61
Valve Lifters, New Type For Past Model Engines	84
Valves, A/C By-Pass, Test Prior to Replacement	37
Valves, Hydrovac Poppet, Replaceable in Field	30
Ventilator Window Regulator, Power, Improved Type	81

W

Warranty Material, Return Labels . .	67
Warranty Parts Shipments Received Damaged	72
Washer, 1957 Windshield, Conditions Diagnosed	21
Washer Hoses, Windshield, Non-Staining Now Used	46
Washer Solvent, Protects Glass Jar From Breaking	79
Water Deflector, Door Inner Panel, Seal Properly	70
Water Leaks Rear Quarter	Supp. 5
Water Leaks, Trunk	16-84
Wheel Bearing, Rear, Cause of Oil Leaks	62
Wheel Bearing, Rear, "O" Ring Seal Improved	65
Whistling Noise at Shift Points, New Cure	27
Wholesale Service Managers	7
Window Frames, Loose Front and Rear Door, Series 75	38
Window Glass, Rear Door, Removal Procedure	30
Window, Improved Type Power Ventilator Regulator	81
Windshield:	
Brougham, Installation Procedure .	61
Sun Glare Can Be Reduced	62
Washer Condition Diagnosed . . .	21
Washer Hoses, Non-Staining, Now Used	46
Wiper Cam Lubrication	40
Wiper Conditions and Their Corrections	20
Wiper Arm Tension, Check, When Wind Lifts Blades	50
Wiper Blades, Longer on Eldorado Brougham	66
Wiper, Windshield, Conditions and Corrections	20
Wire, Autronic Eye, Relocate to Prevent Short	27
Wire Relocations Under Six-Way Power Seat	44

Z

Zipper, Convertible Rear Window, Damaged	29
--	----